


* Uses SCADA
Supervisory
Control
And
Data
Acquisition

Review of phasors

$$v(t) = V_m \cos(\omega t + \theta_v)$$

$$i(t) = I_m \cos(\omega t + \theta_i)$$

$$\omega = 2\pi f$$



$$Z = X + jY$$

$$r = \sqrt{X^2 + Y^2} \quad \theta = \tan^{-1}\left(\frac{Y}{X}\right)$$

$$Z = r(\cos\theta + j\sin\theta)$$

$$e^{j\theta} = \cos\theta + j\sin\theta$$

$$Z = r e^{j\theta}$$

Ex | point in the complex plane

$$p = A \cos(\omega t + \theta)$$

$$r = A$$

$$\theta' = \omega t + \theta$$

Can't simply write $p = Ae^{j\theta'}$


* Extra sine term would be introduced

$$p = \text{Re}\{Ae^{j\theta'}\}$$

$$Ae^{j(\omega t + \theta)}$$

$$Ae^{j\omega t} e^{j\theta}$$

$$(Ae^{j\theta}) e^{j\omega t}$$



Phasor Notation
 $A \cos(\omega t + \theta) \Rightarrow A \angle \theta$

* Note: Must be given as a cosine

$$* \sin(A) = \cos(A - 90^\circ) *$$

$$v(t) = V_m \cos(\omega t + \theta_v)$$

$$i(t) = I_m \cos(\omega t + \theta_i)$$

* Don't write as peak values!! Instead use RMS:

$$\bar{V} = V_{\text{RMS}} \angle \theta_v$$

$$\bar{I} = I_{\text{RMS}} \angle \theta_i$$

$$V_{\text{RMS}} = \sqrt{\frac{1}{T} \int_0^T v^2(t) dt} = \sqrt{\frac{1}{T} \int_0^T V_m^2 \cos^2(\omega t + \theta) dt}$$

$$\cos^2 A = \frac{1 + \cos(2A)}{2}$$

$$\Rightarrow \boxed{V_{\text{RMS}} = \frac{V_m}{\sqrt{2}}}$$

$$\boxed{I_{\text{RMS}} = \frac{I_m}{\sqrt{2}}}$$

2018-08-27-3

Monday, August 27, 2018 10:40 AM

Ex 1

$$v(t) = \sqrt{2}(10) \cos(\omega t + 30^\circ)$$

$$i(t) = \sqrt{2}(5) \cos(\omega t - 20^\circ)$$

$$V_{RMS} = \frac{V_m}{\sqrt{2}} = \frac{\sqrt{2}(10)}{\sqrt{2}} = V_{RMS} = 10 \quad \theta_v = 30^\circ$$

$$I_{RMS} = \frac{I_m}{\sqrt{2}} = \frac{\sqrt{2}(5)}{\sqrt{2}} = I_{RMS} = 5 \text{ A} \quad \theta_i = -20^\circ$$

$$\begin{aligned} \bar{V} &= 10 \angle 30^\circ \text{ V} \\ \bar{I} &= 5 \angle -20^\circ \text{ A} \end{aligned}$$