

In-class assignment and Homework (due 9/30)

- 1. Please read all three SparkFun tutorials listed near the start of unit 2 writeup.
- 2. SPI and I2C BME: Wire up and demonstrate 2 BME sensors, one with I2C interface (original), the other with SPI

Reminder - Homework (due 10/2/2025):

Design a box lid that slides into place instead of just sitting on top of the box. When you're finished with your design, email me both the STL file and the gcode file. Then print and show me the box.